




HerefordHighways @HfdsStreets · 6s

Further images of the dangerous footpath bridge at [#Bodenham](#), showing cracking through the base of the bridge and areas of concrete that have collapsed from the underside. Please do not be tempted to try and use the bridge. [@HfdsCouncil](#)



HerefordHighways @HfdsStreets · 9m



EMERGENCY BRIDGE CLOSURE - [#Bodenham](#) - A well-used public footpath bridge, situated behind St Michael's Church and before River Lugg footbridge, is unsafe and has been closed. Notices are being placed on affected paths. We'll update on timescale for repair aft...

